



View Notice Details

Notice Type CCO Critical  
Notice Identifier 7163  
Notice Name CCO - Exercise Initial - Restore Demand  
Published 25/02/2010 14:59  
Begin Date & Time 25/02/2010 14:59  
End Date & Time 02/03/2010 23:59  
Notice Period 5  
Required Response Indicator Action Required

Detail 25/02/2010  
EXERCISE INITIAL

Exercise Time/Date: 14:00 02 Mar 2010

Direction to Restore Curtailed Demand

This Notice is issued to notify you that the CCO has given direction to restore curtailed demand under Regulation 53 (1) (e) (i)/(ii) of the Gas Governance (Critical Contingency Management) Regulations 2008.

1. Details regarding order for restoration of curtailed demand

No additional instructions.

2. Restoration of curtailed demand now directed

Band 1b Large Consumers; Demand Curtailment Location & Direction  
NPS00530 NEW PLYMOUTH POWER STATION  
BER00653 BERTRAND RD (Methanex)  
NGA00669 NGATIMARU RD (DELIVERY) (Methanex)  
HPS02993 HUNTLY POWER STATION Restore to 11 SCMS by 17:00 02/03/10  
OTB00301 OTAHUHU B POWER STATION Remain offline  
SDN00101 SOUTHDOWN POWER STATION  
TRC02003 TE RAPA COGENERATION PLANT  
BAL08201 BALLANCE AMMONIA-UREA (Fuel)  
BAL09626 BALLANCE AMMONIA-UREA (Process)  
TCC00201 TARANAKI COMBINED CYCLE (TCC)

Bands 2-6; Demand Curtailment Direction  
Band 2  
Band 3  
Band 4  
Band 5  
Band 6

Bands 2-6; Location of Consumers to be curtailed

2. Event causing critical contingency

Landslip over Maui pipeline at Tongapurutu ~20km south of Mokau Compressor Station. Pipeline damage investigated and line found to be buckled. Arrangements now being made to isolate the affected section of pipeline to investigate further and consider repair options.

3. Areas of transmission system affected

Maui pipeline north of Mokau compressor station. Vector northern pipeline and Vector Morrinsville Lateral.

4. Summary of actions being taken to resolve event

Vector has advised that the section of Maui pipeline damaged by the landslip has been cut out and replaced. Line pack is being restored and the demand restoration process is now in progress.

Due to a request by Transpower to restore gas for power generation, the TSO has elected to restore demand in an alternative order.

Notes:

(a) This notice supersedes all previous notices. It includes all demand previously directed for restoration and any additional demands that can now be restored.

(c) Retailers and Large Consumers must follow directions given by TSOs to restore curtailed demand in accordance with Regulation 55(1) and provide TSOs with regular updates of compliance in accordance with Regulation 55(2).

(e) The communication of this notice by email is recorded on the CCO computer system and the notice is considered received by this record. The date and time of this notice is that time stamped by the CCO computer system. It is not required to reply to or acknowledge this email notice.

(g) This notice will be published on the CCO internet site in the public domain. Refer to <https://www.oatis.co.nz>

[Previous](#)