



View Notice Details

Notice Type CCO Critical
Notice Identifier 7169
Notice Name CCO - Exercise Initial - Restore Demand 3
Published 25/02/2010 16:03
Begin Date & Time 25/02/2010 16:02
End Date & Time 02/03/2010 23:59
Notice Period 5
Required Response Indicator Action Required

Detail 25/02/2010
EXERCISE INITIAL

Exercise Time/Date: 22:00 02 Mar 2010

Direction to Restore Curtailed Demand

This Notice is issued to notify you that the CCO has given direction to restore curtailed demand under Regulation 53 (1) (e) (i)/(ii) of the Gas Governance (Critical Contingency Management) Regulations 2008.

1. Details regarding order for restoration of curtailed demand

No additional instructions.

2. Restoration of curtailed demand now directed

Band 1b Large Consumers; Demand Restoration Location & Direction
NPS00530 NEW PLYMOUTH POWER STATION
BER00653 BERTRAND RD (Methanex)
NGA00669 NGATIMARU RD (DELIVERY) (Methanex)
HPS02993 HUNTLY POWER STATION Restore all demand
OTB00301 OTAHUHU B POWER STATION
SDN00101 SOUTHDOWN POWER STATION Restore all demand
TRC02003 TE RAPA COGENERATION PLANT Restore all demand
BAL08201 BALLANCE AMMONIA-UREA (Fuel)
BAL09626 BALLANCE AMMONIA-UREA (Process)
TCC00201 TARANAKI COMBINED CYCLE (TCC)

Bands 2-6; Demand Restoration Direction
Band 2 Restore all demand
Band 3 Restore all demand
Band 4 Restore all demand
Band 5
Band 6

Bands 2-6; Location of Consumers to be Restored

HTK08301 HAMILTON TE KOWHAI
HTV11301 HAMILTON TEMPLEVIEW
HRU16101 HOROTIU
CAM17201 CAMBRIDGE
MTG17301 MATANGI
KIW34201 KIWITAHU (PEROXIDE)
KIW34202 KIWITAHU
MRV16301 MORRINSVILLE DAIRY FACTORY
MRV16302 MORRINSVILLE
TAT16401 TATUA
WTA16501 WAITOA
TUK06501 TUAKAU
HAR11801 HARRISVILLE
PAP06603 PAPAKURA
PAP06610 PAPAKURA
PUK04201 PUKEKOHE
KIG16801 KINGSEAT
GLB03401 GLENBROOK
RAM15201 RAMARAMA
DRU15101 DRURY
DRU15102 DRURY NGC
HUN15301 HUNUA
HUN15302 HUNUA (NOVA)
ALF15501 ALFRISTON
FLB15601 FLAT BUSH
WST03610 WESTFIELD

BMC17901 BRUCE MCLAREN
HEN74101 HENDERSON
WTK33901 WAITOKI
WTK33902 WAITOKI B
WRK18901 WARKWORTH
WEL18301 WELLSFORD
MUT19001 MAUNGATUROTO
MSD01801 MARSDEN POINT DIRECT
MSD01802 MARSDEN POINT
OAK18601 OAKLEIGH
WHG07501 WHANGAREI
KUR33601 KAURI

2. Event causing critical contingency

Landslip over Maui pipeline at Tongapurutu ~20km south of Mokau Compressor Station. Pipeline damage investigated and line found to be buckled. Arrangements now being made to isolate the affected section of pipeline to investigate further and consider repair options.

3. Areas of transmission system affected

Maui pipeline north of Mokau compressor station. Vector northern pipeline and Vector Morrinsville Lateral.

4. Summary of actions being taken to resolve event

Vector has advised that the section of Maui pipeline damaged by the landslip has been cut out and replaced. Line pack is being restored and the demand restoration process is now in progress.

Notes:

(a) This notice supersedes all previous notices. It includes all demand previously directed for restoration and any additional demands that can now be restored.

(b) All directions issued by the CCO pursuant to the declaration of the Critical Contingency must be complied with.

(c) Retailers and Large Consumers must follow directions given by TSOs to restore curtailed demand in accordance with Regulation 55(1) and provide TSOs with regular updates of compliance in accordance with Regulation 55(2).

(d) The communications described in the CCO Communication Plan and TSOs CCMPs continue to be activated.

(e) The communication of this notice by email is recorded on the CCO computer system and the notice is considered received by this record. The date and time of this notice is that time stamped by the CCO computer system. It is not required to reply to or acknowledge this email notice.
Sent by the Critical Contingency Operator